

LIST OF BULLETINS ISSUED FOR L 23 SAILPLANES

No.	Type	Description	Effectiveness
L23/001a	mandatory	Flight Manual Amendment - Chapters 1,4, and 8 Change	Do-L23.1011.3
L23/001d	document.	Maintenance Manual	Do-L23-1031.3
L23/002a	mandatory	A change of the lower tail skid suspension and the reinforcement of the fuselage	897501 - 897520, 907601 - 907614
L23/002d	document.	Maintenance Manual	Do-L23-1031.3
L23/003a	mandatory	Tail skid replacement.	907601 - 907613
L23/003d	document.	Maintenance Manual	Do-L23-1031.3
L23/004a	mandatory	The bottom towing hook is turned of about 10 backwards.	907609 -907611, 907620, 907621
L23/004d	document.	Maintenance Manual	Do-L23-1031.3
L23/005a	mandatory	The Flight Manual small Changes	Do-L23.1011.3
L23/006d	document.	Maintenance Manual	Do-L23-1031.3
L23/007d	document.	Maintenance Manual	Do-L23-1031.3
L23/008a	mandatory	The Flight Manual	Do-L23.1011.3
L23/008d	document.	Maintenance Manual	Do-L23-1031.3
L23/009a	mandatory	Wheel spur adjustment	897501 - 917930
L23/009d	document.	Illustrated Parts Catalogue	Do-L23-2021.3
L23/010a	mandatory	Tail-wheel landing gear is modified - better sprung now.	897501 - 897520, 907601 - 907630, 907701 - 907730, 917801 - 917830, 917901 - 917921
L23/011a	mandatory	Flight Manual and Maintenance Manual Amendments for Aerobatic Operation.	Do-L23.1004.4 Do-L23.1031.4
L23/011d	document.	Maintenance Manual	Do-L23-1031.3
L23/012a	mandatory	The replacement of the adjustment strap of the forward pilot's backrest.	897501 - 897520, 907601 - 907630, 907701 - 907730, 917801 - 917830, 917901 - 917930
L23/012d	document.	Maintenance Manual	Do-L23-1031.3, SN 988313 -988315, 988414

L23/013a	mandatory	Placards are additionally installed in both pilot's cockpits, and a luggage net in the luggage hold.	917803, 917826, 917814 - 917817, 917905, 917906, 917911, 917912, 917914 - 917917, 917921 - 917924, 917926 - 917928, 928001, 928002, 928006, 928007
L23/013d	document.	Maintenance Manual	Do-L23-1031.3
L23/014a	mandatory	Flight Manual - Centre of Gravity Range Extension	Do-L23.1011.3
L23/014d	document.	Maintenance Manual	Do-L23-1031.3
L23/015a	mandatory	Flight Manual Amendment (only in English)	Do-L23.1011.4
L23/015d	document.	Maintenance Manual	Do-L23-1031.3
L23/016a	mandatory	Flight Manual - Max. Speed Limitation (only in Czech language)	Do-L23.1011.1
L23/017a	mandatory	The Flight Manual Do-L23.1011.4 The Maintenance Manual Do-L23.1031.4	938101 and subsequent
L23/017d	document.	Maintenance Manual	Do-L23-1031.3
L23/018a	mandatory	The structure under the rudder footstep bearing is not sufficiently rigid.	897501 - 897520, 907601 - 907630, 907701 - 907730, 917801 - 917830, 917901 - 917930, 928001 - 928010, 938011 - 938030, 938101 - 938110, 948111 - 948130
L23/019b	information	To improve sailplane handling on the ground.	897501 - 897520, 907601 - 907630, 907701 - 907730, 917801 - 917830, 917901 - 917930, 928001 - 928010, 938011 - 938030, 938101 - 938110, 948111 - 948130
L23/019d	document.	Sailplane Flight Manual	Do-L23-1011.3, Do-L23-1011.5, Do-L23-1012.3, Do-L23-1012.5, Do-L23-1012.6, Do-L23-1013.3, Do-L23-1014.5
L23/020a	mandatory	Flight Manual	Do-L23.1011.4 Do-L23.1031.4
L23/020d	document.	Maintenance Manual	Do-L23-1031.3
L23/021a	mandatory	Flight Manual	Do-L23.1012.3
L23/021d	document.	Maintenance Manual Replaced by L23/021d Rev. 1	Do-L23-1031.3
L23/021d Rev. 1	document.	Maintenance Manual Cancels bull. L23/021d	Do-L23-1031.3
L23/022a	mandatory	Wing-tip extensions used on L 23	Do-L 23.1031.3
L23/022d	document.	Maintenance Manual	Do-L23-1031.3

L23/023a	mandatory	Flight Manual	Do-L23-1011.4
L23/023d	document.	Illustrated Parts Catalogue	Do-L23-2021.3
L23/024a	mandatory	The airspeed indicator exchange LUN 1106.10-8 for LUN 1106.22-8	938101 - 938104
L23/025a	mandatory	Flight Manual The Bulletin was not issued in English language.	Do-L23-1012.1
L23/026a	mandatory	Flight Manual Amendment and Small Changes	Do-L23.1012
L23/027a	mandatory	Maintenance Manual Amendment - Part 5 change	Do-L 23.1031.3
L23/028a	mandatory	Maintenance Manual Amendment (only in English language)	Do-L23-1031.3
L23/029a	mandatory	Flight Manual Amendment - variometer ILEC SC-7, indicator RAZ	Do-L23.1012.1 Do-L23.1012.3 Do-L23.1012.5
L23/030a	mandatory	Flight Manual Amendment - preflight checks (only in English language)	Do-L23.1012.5
L23/031a	mandatory	Flight Manual Amendment - transfer to metric units (only in English language)	Do-L23.1012.5
L23/032a	mandatory	Flight Manual Amendment - "Model 96"	Do-L23.1012.3 (CAN) Do-L23.1012.4 (GER) Do-L23.1012.6 (BRAZ)
L23/033a	mandatory	Maintenance Manual for the L23 Super Blaník	Do-L23-1031.3
L23/034a	mandatory	Flight Manual Amendment - "Model 96"	Do-L23.1012.4 (GER)
L23/035a	mandatory	Flight Manual Amendment - insertion of Section 9	Do-L23.1012.3 Do-L23.1012.4 L23.1012.5 Do-L23.1012.6
L23/036a	mandatory	Maintenance Manual for the L23 Super Blaník	Do-L23-1031.3 Do-L23-1031.4
L23/037a	mandatory	Flight Manual Amendment The bulletin was not issued in English language.	Do-L23-1013.1 S/N X-02
L23/038b	information	Resurses of inspection of 2,3,4 types are lengthened by 1 year with all L23 sailplanes	L 23 SUPER-BLANIK
L23/039a	mandatory	Maintenance Manual for L23 Super Blanik	Do-L23-1031.3

L23/040b	information	Establishment of a new company named LETECKÉ ZÁVODY a.s.	L 23 SUPER-BLANIK
L23/041a	mandatory	Maintenance Manual - Chapter 11	L 23 SUPER-BLANIK Do-L23-1031.3
L23/043a	mandatory	Flight Manual - correction of the maximum useful load value	L 23 SUPER-BLANIK Do-L23.1014.5
L23/048a	mandatory	Check of the elevator rockerlever for possible cracks finding	L23 up to S/N 039019
L23/049a	mandatory	Flight Manual-Increase of the maximum take-off L23 weight up to 530 kg	Do-L23.1012.4
L23/050a	mandatory	Check of the control bridge at the place of gripping of control levers in the front and rear cockpit. Replaced by Revision No. 1.	L 23 SUPER-BLANIK
L23/050a	mandatory	Revision No. 1 Supplements information about subsequential routine check at periodic maintenance and supplements information about Bridge older type of design. Replaced by Revision No. 2	L 23 SUPER-BLANIK
L23/050a	mandatory	Revision No. 2 Minor corrections in a text.	L 23 SUPER-BLANIK
L23/051a	mandatory	Checks for cracks at ribs and stringers in areas of wing skin joints at ribs No. 7 and 13.	L 23 SUPER-BLANIK
L23/052a	mandatory	Check of internal elevator hinges on the stabilizer area and its potential replacement.	L 23 SUPER-BLANIK
L23/053a	mandatory	Inspection of welded bracket (Dwg. No. A730 420N) located on the fin.	L 23 SUPER-BLANIK
L23/054b	information	Replacement of A730 420N bracket in case cracks finding in the course of MB L23/053a execution.	L 23 SUPER-BLANIK

L23/054b	information	Revision No. 1 Supplements world-wide available material.	L 23 SUPER-BLANIK
L23/057b	information	Possible lifetime extension	L 23 SUPER-BLANIK

This list of bulletins is up-dated always after issue of new bulletin however not more often than once a month.